



TIRE SERVICE INTERNATIONAL

Model 525 Tire Spinner

buyTSI.com - 800.223.4540



Read this manual before operating

Tire Service International, LLC

201 Chelsea Road
Monticello, MN 55362

Office: 602.437.5020

Email: sales@buytsi.com

Fax: 602.437.5025

Contact us for any assistance

800.223.4540

Revised: June 2024

General Information

The 525 Wheel Spinner is the companion component to the 501A Electronic Strobe Balancer. The Electronic Strobe Balancer delivers fast, precision balancing on the vehicle. No special wheel attachments are required. There is no more accurate way to balance a tire and wheel assembly than on the vehicle. When balancing on the vehicle, the rotor or drum and hub assembly are included which insures a better balance. The 525 Wheel Spinner spins the tires on the vehicle easily.

Safety Requirements

1. Make sure installation conforms to all applicable Local, State, and Federal Codes, Rules, and Regulations; such as State and Federal OSHA Regulations and Electrical Codes.
2. Read and follow the safety instructions. Keep them readily available for machine operators.
3. Make certain all operators are properly trained, know how to safely and correctly operate the unit, and are properly supervised.
4. Allow unit operation only with all parts in place and operating safely.
5. Carefully inspect the unit on a regular basis and perform all maintenance as required.
6. Service and maintain the unit only with authorized or approved replacement parts.
7. Keep all instructions permanently with the unit and all decals/labels/notices on the unit clean and visible.
8. Do not override safety features.
9. Personal protective equipment helps make tire servicing safer. However, equipment does not take the place of safe operating practices.
 - A. Eye protection is essential during tire service activity. Safety glasses with sideshields, goggles, or face shields are acceptable.
 - B. Always wear durable work clothing during tire service activity. Loose fitting clothing should be avoided.
 - C. Tight fitting leather gloves are recommended to protect operator's hands when handling worn tires and wheels.
 - D. Sturdy leather work shoes with steel toes and oil resistant soles should be used by tire service personnel to help prevent injury in typical shop activities.
 - E. Back belts provide support during lifting activities and are also helpful in providing operator protection.
 - F. Consideration should also be given to the use of hearing protection if tire service activity is performed in an enclosed area or if noise levels are high.

FAILURE TO READ AND FOLLOW ALL WARNINGS AND INSTRUCTIONS IN THIS MANUAL CAN LEAD TO SERIOUS PERSONAL INJURY OR DEATH TO OPERATOR OR BYSTANDER.

Installation Requirements

1. The Model 525 Spinner is a heavy duty, continuous service, overload protected auto and truck wheel spinner. It is powered by a 7 1/2 H.P., 3 phase, 50-60 hertz motor.
2. Wiring should be performed by a qualified electrician using #10 wire.
3. Rotation of the spinning bell is clockwise looking into the side of the bell. This making tire being spun to rotate downward at the spinner. This makes the brake work properly.

Operating Instruction

1. Secure the vehicle with appropriate blocks
2. Use a sturdy jack to lift the tire 3 inches to clear the floor
3. Position the 525 unit close to the tire, but not touching
4. Turn on the unit using the toggle switch
5. Push against the wheel until sufficient speed is reached to find the heavy spot using the 501A
6. The brake is slid over spinning bell and applied to the wheel.
7. Weight is applied to light side of wheel as indicated from the balancer
8. The action of spin-up and brake is repeated until the tire is balanced.
9. A balanced tire will have no shake and the 501A will discontinue flashing after balance is within .007 inch tolerance.

Notes

California Proposition 65

California's Proposition 65 entitles California consumers to special warnings for products that contain chemicals known to the state of California to cause cancer and birth defects or other reproductive harm if those products expose consumers to such chemicals above certain threshold levels.

WARNING: Some of Tire Service International's products can expose you to chemicals including chromium compounds, which are known to the State of California to cause cancer, birth defects or other reproductive harm. For more information, go to www.P65Warnings.ca.gov.

Your risk from exposure to these chemicals varies, depending on exposure time. To reduce your exposure, work in a well-ventilated area and with approved safety equipment, such as dust masks that are specially designed to filter out microscopic particles. Wash your hands after touching TSI's products.

Warranty and Return Policy

Warranty & Workmanship you can depend on.

With over 30 years of manufacturing experience we maintain the ability to provide competitive prices while employing and manufacturing the majority of our products in the USA. Pride in our workmanship and standing behind each and every product is not just our claim but our uncompromising responsibility.

Tire Service International equipment is warranted to be free from defects in materials and workmanship for a period of one year from the date of original purchase to the original owner. Repair labor is warranted for 90 days from the date of original purchase. Bushings, blades, bearings and normal wear and tear are not covered under warranty. Careless handling, negligence, misuse, abuse, mutilation, improper operation, making unauthorized repairs, additions, and or alterations automatically cancel this warranty and relieves TSI of any obligation. Cheetah tanks claimed to be defective while under warranty will be evaluated at our manufacturing plant and either repaired if possible or exchanged and returned or credit issued to the customer account at our discretion. Damage resulting from dropping the tanks will not receive warranty consideration. Warranty parts need to be returned prepaid to the plant for credit. Any replacement parts shipped from the plant will be shipped at the customer's expense. Machines requiring warranty work must be brought to the manufacturing plant in 201 Chelsea Rd, Monticello, MN or to a repair facility authorized by TSI.

!!WARNING!! Goods returned without an RGA will be refused. A Returned Goods Authorization form must be obtained before returning any material or goods. All non-warranty returns will be subject to a 15% restocking fee plus any additional charges for reconditioning/repacking.



Visit www.buyTSI.com for any additional information. Also be sure to follow us on all the Socials, and subscribe to our YouTube channel for all our product videos.

No part of this manual may be reproduced without specific approval from
Tire Service International, LLC.

Copyright © 2024 Tire Service International, LLC



buyTSI.com - 800.223.4540